

Fig. 1

ing and the second



Click on the smallest character readable as "8."

Fig. 2



"All unreadable"

Fig. 3 Astigmatic axis measurement chart 1





Fig. 4 Astigmatic axis measurement chart 2



with higher contrast"

with higher contrast"

"All viewed equally"

Fig. 5





Fig. 6 Astigmatic axis measurement chart 3




with higher contrast"

with higher contrast"

Fig. 7

Astigmatic axis measurement chart 3



"One viewed with higher contrast"

"All viewed equally"






Fig. 9






Fig. 10




"None viewed with 3 lines"

Fig. 11



"None viewed with 3 lines"

Fig. 12



"None viewed with 3 lines"

Fig. 13




Fig. 14




Fig. 15




Fig. 16




Fig.17





Fig. 18








Fig. 20




Fig. 21
PRIOR ART




Fig. 22 PRIOR ART

